Industrial Graphite Blocks and Cylinder

- Manufactured from the purest grade industrial graphite
- Weld deposit, welding slag or spatter will not adhere
- Low electrical conductivity
- Chemically inert – won't combine with base metal
- Easily machinable to precise dimensions

Applications

- Use in hardfacing, specifically when building up hammers, teeth, etc.
- Making molds, forms, dies and templates
- Stop weld deposits from filling holes or keyways

Rectangular Graphite Blocks



Thickness (Inches)	Width (Inches)	Length (Inches)	Part No.	Pkg. Qty. (Lbs.)
2	10	12	**CW1494**	15

Cylindrical Graphite Rod

Dia. (Inches)	Length (Inches)	Part No.	Pkg. Qty.
1	12	**CW1496**	3

EZ Purge™ Pre-Formed, Self Adhesive Water Soluble Purge Dams

- Heavy-weight, water soluble purge dam is complete in less than a minute
- Eliminate the need to measure, cut and construct purge dams, saving time and money





1. Peel liner to expose adhesive.
2. Insert EZ Purge™ dam inside pipe.
3. Press tape along circumference to inside of pipe wall.
4. Dissolves instantaneously and completely in water-based liquids.

NOTE: Before using EZ Purge™, be sure to clean the interior of the pipe with EZ Wipes™ (Part No. CW5780) multipurpose saturated cleaning wipes to remove dirt, grease, grime and particles from the pipe surface, ensuring maximum adhesion of the dam.

Size Inches (mm)	Part No.	Pkg. Qty.
2 (51)	**CW5767**	1***
3 (76)	**CW5768**	1***
4 (102)	**CW5770**	1*
5 (127)	**CW5769**	1*
6 (152)	**CW5771**	1*
8 (203)	**CW5772**	1*
10 (254)	**CW5773**	1*
12 (305)	**CW5774**	1*
14 (356)	**CW5775**	1**
16 (406)	**CW5776**	1**
18 (457)	**CW5777**	1**
20 (508)	**CW5778**	1**
24 (610)	**CW5779**	1**

**12 nested in a poly bag*
***6 nested in a poly bag*
****48 nested in a poly bag*

EZ Zone™ Purge Gas Tape

- A purge gas retaining tape used to seal the root gap between pipes to trap argon gas when pipe welding



Application

The adhesive edges stick to the area surrounding the root gap on stainless steel and aluminum pipes with the adhesive-free "zone" being placed over the weld.



Result

Adhesive never comes in contact with the weld joint as it is welded, creating a clean, contaminant-free weld.



Size Inches (mm)	Zone Width Inches (mm)	Length Feet (m)	Part No.	Pkg. Qty.
2-1/2 (64)	1 (25)	75 (23)	**CW5782**	1
4 (102)	2 (50)	75 (23)	**CW5783**	1